















◀ Pagina precedente

Codice	€	Foto	Descrizione	Dimensione	N° Torx®	Sede esagonale (mm)
A910350045	€		Ricambio vite	M4x11,5	20	-
A910350054	€			M4,5x10,5	20	-
A910350055	€			M5x11	20	-
A910350032	€			M4x5	15	-
A910350060	€			M5x12	-	3
A910380005	€			M2x3,3	6	-
A910380010	€			M2,5x4,2	8	-
A910380015	€			M2,5x5	8	-
A910380020	€			M3x7,3	8	-
A910380025	€			M3,5,x8,2	15	-
A910380030	€			M5x8,8	20	-
A910380035	€			M6x12	25	-
A910400005	€				Ricambio vite	M3,5x3,3
A910400010	€	M3,5x4,2	9			-
A910400015	€	M4x5,2	15			-
A910400020	€	M4x7,8	15	-	-	
A910430005	€		Ricambio sottopiacchetta	-	-	-
A910450005	€		Ricambio sottopiacchetta	-	-	-
A910450010	€		Ricambio sottopiacchetta	-	-	-
A910500005	€		Ricambio sottopiacchetta	-	-	-
A910500010	€			-	-	-
A910550005	€		Ricambio sottopiacchetta	-	-	-
A910550010	€			-	-	-
A910600005	€		Ricambio sottopiacchetta	-	-	-
A910650005	€		Ricambio cassetta	-	-	-
A910700005	€		Ricambio cassetta	-	-	-
A910750005	€		Ricambio staffa	-	-	-
A910800005	€		Ricambio anello refrigerante	-	-	-
A910850005	€			-	-	-
A915800005	€		Perno	M8x30,5	-	-
A915800010	€			M10x31	-	-
A915800015	€			M12x30	-	-
A919000080	€		Ricambio vite	-	-	-
A919000090	€			-	-	-
A919000100	€			-	-	-
A919000120	€			-	-	-
A919000140	€			-	-	-
A919000160	€			-	-	-
A919000180	€			-	-	-
A919000200	€			-	-	-
A919000220	€			-	-	-
A919000240	€			-	-	-
A919000260	€			-	-	-
A919000280	€			-	-	-
A919000300	€			-	-	-
A919000320	€			-	-	-
A919000360	€			-	-	-
A919000400	€			-	-	-
A919000450	€			-	-	-
A919050005	€			M3,5x7,2	T15	-
A919050010	€			M3,5x8,6	T15	-
A919050015	€			M4,5x10,5	T20	-