










Fresatura		P	M	K	N	S	H
WCHX 040102EN-BFM LCM45T	RP300	P30-P40	M30-M40				
WCHX 040104EN-BFM LCM45T							
WCHX 05T102EN-BFM LCM45T							
WCHX 05T104EN-BFM LCM45T							
WCHX 060202EN-BFM LCM45T							
WCHX 060204EN-BFM LCM45T							
WCHX 070304EN-BFM LCM45T							
WCHX 070308EN-BFM LCM45T							
WCHX 090304EN-BFM LCM45T							
WCHX 090308EN-BFM LCM45T							
WCHX 10T304EN-BFM LCM45T							
WCHX 10T308EN-BFM LCM45T							
WCHX 130508EN-BFM LCM45T							
	fz	0,01-0,13	0,01-0,13				
	ap						
	VC	70-50	50-150				
WNEU 040308-MM	RK300	P25-P40	M20-M40	K20-K40			
	fz	0,10-0,30	0,10-0,30	0,10-0,30			
	ap	0,5-3,5	0,5-3,5	0,5-3,5			
	VC	110-200	50-120	120-200			
WNEU 040308-MM	RP300	P25-P40	M30-M40				
	fz	0,10-0,30	0,10-0,30				
	ap	0,5-3,5	0,5-3,5				
	VC	110-200	60-130				
WNEU 040308-MM	RP200	P10-P20		K10-K20			
	fz	0,10-0,30		0,10-0,30			
	ap	0,5-3,5		0,5-3,5			
	VC	110-220		110-220			
WNEU 080608-MB	RK300	P25-P40	M20-M40	K20-K40			
	fz	0,10-0,30	0,10-0,30	0,10-0,30			
	ap	0,5-6	0,5-6	0,5-6			
	VC	110-200	50-120	120-200			
WNEU 080608-MB	RP300	P30-P40	M30-M40				
	fz	0,10-0,30	0,10-0,30				
	ap	0,5-6	0,5-6				
	VC	100-170	60-130				
WNEU 080608-MB	RP200	P10-P20		K10-K20			
	fz	0,10-0,30		0,10-0,30			
	ap	0,5-6		0,5-6			
	VC	110-220		110-220			
WNEX 080608 ALU	NK15				K10-K20		
	fz				0,10-0,30		
	ap				0,5-6		
	VC				300-500		
XPMT 042004	RP300	P10-P30	M20-M35	K10-K30			
XPMT 052804							
XPMT 063306							
XPMT 074006							
XPMT 094508							
XPMT 125812							
XPMT 156812							
	fz	0,06-0,15	0,06-0,15	0,06-0,2			
	ap						
	VC	150-200	140-190	180-230			