














Tornitura		P	M	K	N	S	H
	RK400	P20-P35	M10-M25	K10-K20			
	fz	0,03-0,15	0,03-0,15	0,03-0,15			
	VC	100-190	70-90	120-200			
CCGT 0602 02/04	NK15				K10-K20		
CCGT 09T3 02/04/08		fz			0,05-0,20		
CCGT 1204 02/04/08		VC			160-250		
	RK400	P10-P30	M10-M25	K10-K20			
	fz	0,07-0,17	0,06-0,14	0,06-0,15			
	VC	120-250	80-220	120-230			
	RK400	P10-P30	M10-M25	K10-K20			
	fz	0,09-0,20	0,08-0,26	0,08-0,20			
	VC	120-250	80-220	120-230			
	RK400	P10-P30	M10-M25	K10-K20			
	fz	0,18-0,45	0,18-0,35	0,15-0,50			
	VC	120-250	80-220	120-230			
	NK15				K10-K15		
	fz				0,03-0,12		
	VC				160-250		
	RK400	P20-P35	M15-M30	K15-K25			
	fz	0,03-0,15	0,03-0,15	0,03-0,15			
	VC	110-190	70-90	120-200			
	RK400	P10-P30	M10-M25	K10-K20			
	fz	0,18-0,15	0,18-0,35	0,15-0,55			
	VC	120-250	70-220	120-230			
	NK15				K10-K15		
	fz				0,03-0,12		
	VC				160-250		
	NK15				K10-K15		
	fz				0,02-0,15		
	VC				160-250		
	RK400	P20-P35	M15-M30	K15-K25			
	fz	0,05-0,20	0,05-0,20	0,05-0,20			
	VC	100-190	70-90	120-200			
	NK15				K10-K20		
	fz				0,08-0,20		
	VC				160-250		