













Tornitura		P	M	K	N	S	H
DCGT 11T302		NK15			K10-K20		
DCGT 11T3 04/08							
fz							
	VC				160-250		
DCMT 0702 02/04		RK400	P10-P30	M10-M25	K10-K20		
fz			0,07-0,17	0,06-0,14	0,06-0,15		
VC			120-250	80-220	120-230		
DCMT 11T3 02/04/08		RK400	P10-P30	M10-M25	K10-K20		
fz			0,18-0,45	0,18-0,35	0,15-0,55		
VC			120-250	80-220	120-230		
DNMG 150608		RK400	P10-P30	M10-M25	K10-K20		
fz			0,18-0,45	0,18-0,35	0,15-0,55		
VC			120-250	70-220	120-230		
SCGT 09T3 04/08		NK15			K10-K20		
SCGT 120408							
fz							
	VC				160-250		
SCMT 060204		RK400	P15-P30	M20-M35	K15-K30		
fz			0,05-2	0,05-2	0,05-2		
VC			100-240	130-220	120-200		
SCMT 09T308		RK400	P10-P30	M10-M25	K10-K20		
fz			0,18-0,45	0,20-0,40	0,15-0,50		
VC			120-250	80-220	120-230		
SCMT 120408		RK400	P10-P30	M10-M25	K10-K20		
fz			0,13-0,30	0,20-0,40	0,15-0,50		
VC			120-250	110-170	120-230		
SNMG 120408		RK400	P10-P30	M10-M25	K10-K20		
fz			0,15-0,56	0,25-0,49	0,21-0,77		
VC			120-250	80-220	120-230		
TCGT 1102 02/04		NK15			K10-K20		
TCGT 16T3 04/08							
fz							
	VC				160-250		
TCMT 1102 02/04		RK400	P10-P30	M10-M25	K10-K20		
fz			0,08-0,17	0,06-0,16	0,06-0,15		
VC			120-250	80-220	120-230		
TCMT 16T3 04/08		RK400	P10-P30	M10-M25	K10-K20		
fz			0,10-0,20	0,08-0,16	0,08-0,18		
VC			120-250	80-220	120-210		