















← Pagina precedente

Codice	Foto	Descrizione	Dimensione	N° Torx®	Sede esagonale (mm)	€
A910350045		Ricambio vite	M4x11,5	20	-	7,77 ◆
A910350054			M4,5x10,5	20	-	7,77 ◆
A910350055			M5x11	20	-	7,77 ◆
A910380005			M2x3,3	6	-	7,77 ◆
A910380010			M2,5x4,2	8	-	7,77 ◆
A910380015			M2,5x5	8	-	7,77 ◆
A910380020			M3x7,3	8	-	7,77 ◆
A910380025			M3,x8,2	15	-	7,77 ◆
A910380030			M5x8,8	20	-	7,77 ◆
A910380035			M6x12	25	-	7,77 ◆
A910400005		Ricambio vite	M3,5x3,3	9	-	7,77 ◆
A910400010			M3,5x4,2	9	-	7,77 ◆
A910400015			M4x5,2	15	-	7,77 ◆
A910400020			M4x7,8	15	-	7,77 ◆
A910430005		Ricambio sottopiacchetta	-	-	-	7,77 ◆
A910450005		Ricambio sottopiacchetta	-	-	-	7,77 ◆
A910450010			-	-	-	7,77 ◆
A910500005		Ricambio sottopiacchetta	-	-	-	7,77 ◆
A910500010			-	-	-	7,77 ◆
A910550005		Ricambio sottopiacchetta	-	-	-	7,77 ◆
A910550010			-	-	-	7,77 ◆
A910600005		Ricambio sottopiacchetta	-	-	-	7,77 ◆
A910650005		Ricambio cassetta	-	-	-	7,77 ◆
A910700005		Ricambio cassetta	-	-	-	7,77 ◆
A910750005		Ricambio staffa	-	-	-	7,77 ◆
A910800005		Ricambio anello refrigerante	-	-	-	7,77 ◆
A919000080		Ricambio vite	-	-	-	7,77 ◆
A919000100			-	-	-	7,77 ◆
A919000120			-	-	-	7,77 ◆
A919000140			-	-	-	7,77 ◆
A919000160			-	-	-	7,77 ◆
A919000180			-	-	-	7,77 ◆
A919000200			-	-	-	7,77 ◆
A919000220			-	-	-	7,77 ◆
A919000240			-	-	-	7,77 ◆
A919000260			-	-	-	7,77 ◆
A919000280			-	-	-	7,77 ◆
A919000300			-	-	-	7,77 ◆
A919000320			-	-	-	7,77 ◆
A919000360			-	-	-	7,77 ◆
A919000400			-	-	-	7,77 ◆
A919000450			-	-	-	7,77 ◆